

APPENDIX E

- **Proposed Sanitary Landfill
Plates 1 to 9**



Plate 1: View looking northward from the ridge of the sanitary landfill. Vegetation is mainly scrub with scattered pine.



Plate 2: Typical erosion channel running along slope of ridge. Frame shows effect of erosion on exposed ground. These channels are along the southern slope.



Plate 3: Denuded landscape along portions of the western slope.



Plate 4: Disturbed landscape along portions of the eastern slope.



Plate 5: Typical vegetation structure over most of the proposed site.



Plate 6: Typical view of broadleaf transitional forest structure which is conspicuous along western boundary of site.



Plate 7: plate showing good pine regeneration over large areas of the site.



Plate 8: Small seasonal stream running along the southern boundary of the landfill site.



Plate 9. Deep erosion channels draining into seasonal streams along southern slope. Note sparse vegetation.